

# Apple fixes the problem of connecting the MacBook Pro to Cinema Display

The latest Mac OS X update version helps the 2011 MacBook Pro terminate the flashing image condition when connected to Cinema Display 24 and 27 inches.

**The latest Mac OS X update version helps the 2011 MacBook Pro terminate the flashing image condition when connected to Cinema Display 24 and 27 inches.**



Software update for new Mac OS X.

The update to Mac OS X 10.6.7 may be small for most Macs, except for those who are using the MacBook Pro version 2011. According to Apple, with the new version, this model will "improve performance." *Compatibility and stability when displayed with external devices*". Specifically, the MacBook Pro will be fixed to display images that are constantly flashing or break frames when connected to Apple's 24-inch and 27-inch Cinema Display screens.

The first users to download the upgrade and the actual test showed that the above error phenomenon no longer occurs. As such, the previous display error on the MacBook Pro may be due to software bugs only, not the Thunderbolt port, the latest connectivity standard and the first appearance on this MacBook Pro this year.

Mac users will be automatically notified by the system of these new updates to install.

You finished reading the article "**Apple fixes the problem of connecting the MacBook Pro to Cinema Display**" edited by the [TipsMake](#) team. We hope this article has provided you with many useful tech tips and tricks. You can search for similar articles on tips and guides. Thank you for reading and for following us regularly.