

Apple fixes the trackpad error on the 2012 MacBook Pro

The new patch released by the company to fix the trackpad error receiving commands is inconsistent with user actions.

The new patch released by the company to fix the trackpad error receiving commands is inconsistent with user actions.



The new MacBook Pro uses the ultra-high resolution Retina display. (Photo: Engadget).

After just updating the bug fix for the Retina screen of the new MacBook Pro, Apple has just released a patch for the trackpad bug on this product. *Patchpad Update 1.0 " MacBook Pro (Retina)"* is intended to correct trackpad errors without receiving commands consistent with user actions.

The update for Apple's trackpad has a capacity of 1.26MB. Users can download it via Software Update or Apple support website.

The 2012 MacBook Pro has just been introduced on June 12. This product uses ultra-thin IPS panel with a high resolution of 1,280 x 1,800 pixels for a pixel density of up to 220 ppi on an area of 15.4 inches. Apple's new laptop weighs 2.02 kg and is 1.8cm thin. The new MacBook Pro is equipped with a quad-core Core i7 chip with 2.3GHz speed, 8GB of RAM, 256GB SSD, Nvidia GeForce GT 650M graphics card and has a starting price of \$ 2,199.

You finished reading the article "**Apple fixes the trackpad error on the 2012 MacBook Pro**" edited by the [TipsMake](#) team. We hope this article has provided you with many useful tech tips and tricks. You can search for similar articles on tips and guides. Thank you for reading and for following us regularly.
