

# Samsung Galaxy Buds encountered an error while updating the R170XXU0ATD2 firmware

Many users have confirmed that after updating the R170XXU0ATD2 firmware for Samsung Galaxy Buds, there was a connection error on the device.

Samsung has released the firmware version R170XXU0ATD2 for Samsung Galaxy Buds a few days ago, but many people are reflecting that their headphones after updating to this latest version have a few bugs, affecting the use. Use and experience the new features on this update.

R170XXU0ATD2 firmware is currently the latest version for Samsung Galaxy Buds, according to the official announcement from the company, which provides some features of the Galaxy Buds +. Accordingly, Microsoft's Swift Pair feature has also been used on Galaxy Buds, making it easy for users to pair headsets with PCs running Windows 10, to increase the experience of pairing headphones on mobile devices and computers. . In addition to the Spotify music streaming service introduced on Galaxy Buds +, it is now available on Galaxy Buds.



## < Update earbuds software

The latest system software was downloaded.

- Version : R170XXU0ATDz
- Size : 1.39 MB

### What's new

- Sound quality optimization code has been applied.
- "Ambient sound" feature works connected with touch-sensitive sensor and works even when wearing only one earbud.
- "Swift pair" is supported when connecting to Microsoft Windows. (Windows 10, 1803 version or higher)
- Music app list has been added in a preset tap-and-hold feature
  - Supported app : FLO, Genie, Melon, Spotify
- \* Please use it after downloading the supported app in your smartphone.

[www.samsungmobile.com](http://www.samsungmobile.com)

### Caution

- You won't be able to use your earbuds while installing the update.
- Some settings for your earbuds may change.

Later

Install now

The error of this R170XXU0ATD2 firmware update has been reflected by many users on Samsung social networks and product forum pages, with a detailed description of the problem, including connection problems. For devices, the problem with Ambient Mode or the touch control system does not work.

Samsung has not made any official announcement to the tech community about this error on R170XXU0ATD2, but has quietly released the firmware R170XXU0ATD3 although there is no information that is a fix. But a few people who upgraded R170XXU0ATD3 for Galaxy Buds noticed that the headset no longer had a touch-control system error.

## < Update earbuds software

### Copying software update...

- Version : R170XXU0ATD3
- Size : 1.39 MB

### What's new

- Sound quality optimization code has been applied.
- "Ambient sound" feature works connected with touch-sensitive sensor and works even when wearing only one earbud.
- "Swift pair" is supported when connecting to Microsoft Windows.(Windows10, 1803 version or higher)
- Music app list has been added in a preset tap-and-hold feature
  - Supported app : FLO, Genie, Melon, Spotify
- \* Please use it after downloading the supported app in your smartphone.

[www.samsungmobile.com](http://www.samsungmobile.com)

### Caution

- You won't be able to use your earbuds while installing the update.
- Some settings for your earbuds may change.

0.20MB/1.39MB

14%



You finished reading the article "**Samsung Galaxy Buds encountered an error while updating the R170XXU0ATD2 firmware**" edited by the [TipsMake](#) team. We hope this article has provided you with many useful tech tips and tricks. You can search for similar articles on tips and guides. Thank you for reading and for following us regularly.

---